Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight ***DHR Id#:*** **046-5061**

Resource Identification

Property Name(s): ..... House (vacant and overgrown) {}
Property Date: ..... ca 1900
Address(s): ..... South Side of Old Suffolk Road {}
County/Independent City: Isle Of Wight
City: ....
State, Zip: .....Virginia
USGS Quad Name: ..... WINDSOR
Surrounding area: ..... Rural

National Register Eligibility Status
Property is Historic (50 years or older)

Property has been recommended Not Eligible for listing

Resource Description

Ownership Status: ..... Private

Primary Resource Exterior Componant Description:

Component	Comp Type/Form	Material	Material Treatment
Chimneys	Chimneys - Interior end	Brick	Chimneys - Common Bond
Roof	Roof - Gable, Side	Metal	Roof - Standing Seam
Structural System	Structural System - Frame	Wood	Structural System - Weatherboard
Windows	Windows - Double-hung	Wood	Windows - 6/6

Site Description: ..... This house is vacant and the surrounding property is overgrown with thick vegetation. This house is not visible from the street.

Secondary Resource Desc: There are three outbuildings associated with this proeprty.

WUZIT Count:

No.	Wuzit Types	Historic?
1	House	Historic
1	Shed	Historic
1	Tenant House	Historic
1	Privy	Historic

NR Resource Count:

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight **DHR Id#: 046-5061**

Individual Resource Information

WUZIT: ..... Shed

Est. Date of Construction:	1900 ca {Site Visit}	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Fair
Interior Plan Type:		*Threats to Resource:*	Neglect Transportation Expansion

Description: Southwest is a gabled shed that features a weatherboard exterior and gabled roof clad in standing-seam metal.

WUZIT: ..... Privy

Est. Date of Construction:	1900 ca	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Fair
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: Northeast of the house is a privy with a weatherboard clad exterior and a gabled roof covered in standing-seam metal.

WUZIT: ..... Tenant House

Est. Date of Construction:	1900 ca {Site Visit}	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Fair
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion Neglect

Description: Northeast of the house is a small tenant house with a weatherboard clad exterior and a gabled roof covered in standing-seam metal.

WUZIT: ..... House

Est. Date of Construction:	1900 ca {Site Visit}	*Accessed?*	No
Primary Resource?	Yes	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Fair
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion Neglect

Description: Built c. 1900, this one-story Frame Vernacular style house features a wooden frame structural system that rests on a brick foundation. The exterior of this house is covered in weatherboard and the side-gabled roof is clad in standing-seam metal. Fenestration consists of six-over-six wooden double-hung sash windows. This house is currently vacant and overgrown with vegetation. The dense foliage surrounding the house obscures the view of this resource.

Cemetery Information

Bridge Information

National Register Eligibility Information (*Intensive Level Survey*)

Historic Context(s): ..... Domestic

Historic Time Period(s): ..... P- Reconstruction and Growth (1865 to 1914)

Significance Statement: Though this house is currently in good condition, its design is common for the period of construction. This resource has no apparent association with any event or person important in our nation's history, lacks architectural significance, and does not appear to have the ability to yield important information. The resource is recommended as not eligible for the NRHP under Criteria A, B, C, or D.

Bibliographic Documentation

Reference #: 1
Bibliographic RecordType: ..... Survey
Author: ..... CCR, Inc.
Citation Abbreviation: .....
Notes: ..... VDHR # 2002-1760
VDOT # 0460-969-101, PE-101
Architectural Survey, Route 460
Corridor Study

Ownership Information

Graphic Media Documentation

Medium	*Depository ID #*	*Photo Depository*	*Date*	*File Name*
35mm B&W	5	VDHR	2004/07/01	Single Dwelling

Cultural Resource Management (CRM) Events

CRM Event # 1,
Cultural Resource Management Event: ..... Phase I Survey
Date: 2004/08/31
Organization or Person: ..... CCR, Inc.
VDHR Project ID # Associated with Event: .. 2002-1760
CRM Event Notes or Comments: ..... VDHR # 2002-1760
VDOT # 0460-969-101, PE-101
Architectural Survey, Route 460
Corridor Study

CRM Event # 2,
Cultural Resource Management Event: ..... DHR Staff: Not Eligible
Date: 2004/11/18
Organization or Person: .....
VDHR Project ID # Associated with Event: .. 2002-1760
CRM Event Notes or Comments: .....